FIGURE I

PCE PLUME (µg/L) IN THE ALLUVIAL
AQUIFIER AT THE MAINTENANCE SHOP AREA
1ST QUARTER/MARCH 2000



e:\005\260.dgn 06/14/01 04:16:10 PM